

APR 21 2009

The Boeing Company
P.O. Box 3707
Seattle, WA 98124-2207

DEPT OF TRANSPORTATION
DOCKETS

B-H210-09-00208

2009 MAY -5 P 4:41

Docket Management Facility
U.S. Department of Transportation
400 Seventh Street SW
Nassif Building, Room PL-401
Washington, DC 20590
Attention: Airworthiness Rules Docket No. FAA-2009-0293



BOEING

Subject: Comments to NPRM Docket No. FAA-2009-0293 (Directorate Identifier 2008-NM-221-AD) Trailing Edge Flap No Back Brake Boeing Model 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, and 747SR Series

Boeing has reviewed the subject NPRM and concurs with the contents of the proposed rule. Therefore, no additional comments will be forthcoming.

Very truly yours,



B. C. Linder
Manager, Continued Airworthiness
Twin Aisle Programs
B-H210, M/C 0A-87, (425) 717-9352
FAX: (425) 342-3716

bdb